

United States of America
Department of Transportation -- Federal Aviation Administration
Supplemental Type Certificate

Number ST01459WI-D

This certificate, issued to Rockwell Collins, Inc.
400 Collins Road NE, MS 164-100
Cedar Rapids, IA 52498

*certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part * of the **
Regulations.

Original Product - Type Certificate Number : * *See attached FAA Approved Model List (AML)
Make : * No. ST01459WI-D for list of approved airplane models
Model : * and applicable airworthiness regulations.

Description of Type Design Change: Rockwell Collins DLM-900 ACARS CORE Software Upgrade in accordance with Collins Drawing Index as listed on AML No. ST01459WI-D, issued November 26, 2007, or later FAA approved amendment.

Limitations and Conditions:

- (1) Prior installation and approval of a Collins DLM-900 ACARS is required.
- (2) Approval of this change in type design applies to the above model aircraft only.
- (3) Compatibility of this design change with previously approved modifications must be determined by the installer.
- (4) A copy of this Certificate and FAA Approved Model List (AML) No. ST01459WI-D issued November 26, 2007, or later FAA approved amendment, must be maintained as part of the permanent records for the modified aircraft.
- (5) If the holder agrees to permit another person to use this certificate to alter the product, the holder shall give the other person written evidence of that permission.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked, or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application : August 16, 2007

Date reissued :

Date of issuance : November 26, 2007

Date amended :



By direction of the Administrator

A handwritten signature in black ink, appearing to read "John S. Bohn".
(Signature)

John S. Bohn

Administrator, DAS-500864-CE

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.